Road Safety Plan

APPENDIX 1

School	School Crossing Patrol Service Provided	Engineering Measures Provided	Flashing Warning Lights and signs Provided
Primary Schools (31)			
Babbacombe Primary School. TORQUAY	Redenhill Rd / Quinta Rd/ Warboro Rd junction	Dropped kerbs, red anti skid crossing point, road markings to diagram no. 545	4 signs with automatic flashers approaching SCP site. Upgraded to GMS (mobile phone control) 2010/2011
Barton Primary and Nursery. TORQUAY	Barton Road outside school entrance	Road narrowing, barriers, car park, red anti skid crossing point, road markings to Diag.No 545 -SCP site upgraded to new zebra crossing facility.	2 signs with double flashers approaching SCP site. Signs / flashers replaced and upgraded to GMS (mobile phone control) 2008/2009
Brixham Infants and Nursery. BRIXHAM	Higher Ranscombe Road outside school entrance	New standing area with drop crossings and railings. Following redevelopment of the school, improvements have been undertaken to relocate the school crossing patrol at the new school entrance, this included alterations to the kerb lines and the provision of new high friction surfacing and pedestrian guard rails.	due to redevelopment.
Cockington Primary School. TORQUAY	Avenue Road back entrance. Old Mill Rd main entrance.	Old Mill Road new kerb alignment, thermo plastic feet markings, entrance signing. Red anti skid crossing point, road markings to diagram no. 545 on both sites	2 signs with double flashers approaching Avenue Road SCP. 2 signs and single flashers approaching Old Mill Road SCP
Collaton St Mary. PAIGNTON	No	Puffin crossing installed and a new school entrance. Pedestrian guardrails.	Existing signs present
Curledge Street Primary. PAIGNTON	Dartmouth Road Curledge Street	Dartmouth Road junction improvement with footway widening. Curledge Street footway widening both sides, safety barriers, bollards, seats. Red anti skid crossing point, road markings to diagram no. 545 on both sites. New Lighting to Station lane car park with parking permit scheme.	Dartmouth Road 2 signs with flashers on each side of road on each approach to SCP. Curledge Street 1 sign and flasher approaching SCP site (one-way street). Upgraded to GMS (mobile phone control) 2010/2011
Eden Park Infants. BRIXHAM	Drew Street	New footway build-outs, bollards, red anti skid crossing point, road markings to diagram no. 545 Burton St. pavement widening. As part of the Higher Brixham Traffic Action Zone the existing red anti-skid surfacing was renewed and shared space in both Knick Knack Lane and Penn Lane formalised with buff high friction surfacing and appropriate signage.	2 signs with flashers approaching SCP Burton Street 2 signs

Eden Park Juniors	As above	As above	As above
Ellacombe Primary. TORQUAY	Ellacombe Church Road	SCP relocated footpath widened, red anti skid crossing point, road markings to diagram no. 545.	2 pairs of double flashers approaching school 2 single approaching SCP
Furzeham. BRIXHAM	No	New link footpath between school and residential area to the east. New footway links along the playing field to the west. New bus stop facility.	Existing signs present
Galmpton, BRIXHAM	No	New length of footway and widening on opposite side with drop crossing. Installation of Bollards.	2 new signs on approach to school entrance
Hayes. PAIGNTON	Totnes Road	Kerb buildout at rear entrance SCP site, bollards, pedestrian guard rail, realignment of road markings. Footway works carried out to improve the safety of pedestrians crossing the junction of Collingwood Road / Hartley Road and Hayes Road. Works were undertaken on Totnes Road to upgrade the zebra crossing near the junction of Elmbank Road with the fitment of internally illuminated poles and LED halos around the beacons to improve pedestrian links. Footway works were undertaken on Hayes Road at the junction of Derrell Road / Elmbank Road and on Derrell Road (fronting the upgraded play park) to improve pedestrian links.	2 new signs and flashers on approach to rear school entrance SCP site Upgraded to GMS (mobile phone control) 2010/2011
Chestnut. BRIXHAM	No	As part of the Higher Brixham Traffic Action Zone works were undertaken on Milton Street to improve pedestrian access in the vicinity of Pack Hall Lane.	Existing
Homelands. TORQUAY	Crossing	Footway widening, zebra crossing, bollards and guard rail	School signing and Patrol signing with flashers one double (southbound) and single (northbound). Upgraded to GMS (mobile phone control)
llsham. TORQUAY	No	Kerb-buildout, bollards and slow road markings.	Signing on each approach to school entrance Upgraded to GMS (mobile phone control)
Kings Ash Infants and Nursery. PAIGNTON (formerly know as Foxhole)	Fernicombe Road	safety barriers, red anti skid crossing	

		work included alterations to the kerb lines, and the provision of new high friction surfacing and pedestrian guard rails.	
Kings Ash Juniors (formerly known as Foxhole)	As above	As above	As above
Preston. TORQUAY	Position currently being advertised	No	Existing Upgraded to GMS (mobile phone control) 2010/2011
Priory. TORQUAY	No	Improved pedestrian footways with traffic calming and congestion reduction measures.	Existing school signing on
Queensway. TORQUAY	Queensway	Speed cushion traffic calming scheme, drop kerbs and railings.	Patrol sign with double flashers (northbound) and sign with single flasher (southbound) Upgraded to GMS (mobile phone control) 2010/2011
Roselands. PAIGNTON	No	Footstep markings.	Existing signs
Sacred Heart. PAIGNTON	Cecil Road	Drop crossings. Red crossing point, anti skid surfacing and road markings to diagram no. 545. Installation of Guard- rails	Patrol sign with single flasher on each approach
Sherwell Valley, TORQUAY	Hawkins Avenue	Footway widening and dropped kerbs. Red crossing point , anti skid surfacing and road markings to diagram no. 545 Upper Cockington Lane Kerb buildout with bollards. Domed mini roundabout and improved visibility on island crossing.	Hawkins Ave. Patrol sign with single flasher on each approach Upper Cockington Lane school signs Marldon Road school signs and automatic flashers Upgraded to GMS (mobile phone control) 2010/2011
Shiphay. TORQUAY	Exe Hill	Speed cushion traffic calming scheme, drop kerbs and railings.	Patrol sign with single flasher on each approach. Sign / flasher replaced and upgraded to GMS (mobile phone control) 2008/2009
St Margaret Clitherow. BRIXHAM	No	As part of the Higher Brixham Traffic Action Zone a virtual footway was implemented on Horsepool Street, along with slow road markings and traffic calming. A short section of Dashpers was made 'One-Way' to improve pedestrian safety.	Existing
St Margarets TORQUAY	No	Kerb build out railings and bollards.	Existing
	Petitor Road	Hartop Road/Petitor Road widened footway SCP refuge, bollards and railings. Teignmouth Road widened footway, drop crossings. Red crossing point, anti skid surfacing and road markings to diagram no. 545 at both sites	Hartop Road School sign and patrol sign with flasher. Petitor Road Patrol sign with flasher. Teignmouth Road patrol signs with flasher both approaches.
Torre. TORQUAY	No	Footpath widening (existing speed	Existing

		humps scheme).	
Upton St James. TORQUAY	Forrest Road	Forest Road dropped crossings, red crossing point, anti skid surfacing and road markings to diagram no. 545 St. James Road kerb buildout, bollards railings and new TRO's Teignmouth Road improved crossing point with parking permit scheme. Improvements to Lymington Road including New pedestrian Crossing.	4 Patrol signs with single flasher on each approach. School sign on approach to school annexe. Upgraded to GMS (mobile phone control)
Warberry. TORQUAY	Cedars Road	Kerb build out with priority give way, railings, bollard, parents waiting area, TRO's Windsor Road new footway link Lyme View Road footway link	Windsor Road school signing Cedars Road new street lighting, signing and flashers planned for 2004
Watcombe. TORQUAY	No	Alternative kerb build out scheme traffic calming scheme.	Existing
White Rock. PAIGNTON	No	Bollards at the entrance. New parking restrictions introduced around the school entrances.	Existing
Secondary Schools	(8)		
Brixham Community College.	Higher Ranscombe Road	As Brixham infants school	As Brixham infants school
Churston Ferrers Grammar	No	New footway and bus drop-off/ collection area. Virtual footway installed on Greenway Road, pedestrian guard rail upgraded at Dartmouth Road / Greenway Road junction in 2010.	School signing on each approach. Signs upgraded on Dartmouth Road in 2010
St Cuthbert Mayne. TORQUAY	No	Bus parking facilities improved. New kerb build out constructed to slow traffic on approach to bus parking, pedestrian guard rail and signs upgraded in 2010.	Existing Signs upgraded in 2010
Paignton Community College (Lower school) Waterleat Road	No	Waterleat Road Traffic calming.	
Paignton Community College (upper school) Borough Road	Totnes Road	Drop crossings. Red crossing point, anti skid surfacing and road markings to diagram no. 545. Junction improvement to junction of Borough Road and Totnes Road. Improvements to Borough Road including kerb build outs to assist pedestrians, HGV ban and parking restrictions. Cycle way constructed to link school with existing route.	each approach. School signing on each approach
Torquay Boys Grammar	No	Pedestrian phase added to traffic lights.	Existing
Torquay Community College	No	Automatic lights and zebra crossing.	Existing Some signs upgraded during 2010.

Torquay Girls Grammar	No	New puffin crossing	Existing
Westlands Bi-lateral. TORQUAY	No	No	Existing
Special Schools (3)			
Combe Pafford. TORQUAY	No	As Watcombe, TRO,s	Existing
Torbay school. PAIGNTON	No	No	Existing
Mayfield. TORQUAY	No	As Watcombe	Existing
Private Schools (3)			
Tower House School	No	No	Existing
Stoodley Knowle TORQUAY	No	Kerb build out, bollards	Existing
The Abbey. TORQUAY	No	Pedestrian phase at junction access to car park.	Existing.

All schools have a No Stopping Clearway on the school entrance markings. Some schools had their markings refreshed as part of TOR2's ongoing maintenance regime. Note :